



| DIM | TOL |
|----------|------|
| 5mmDOWN | ±0.2 |
| 5~20mm | ±0.3 |
| 20~40mm | ±0.4 |
| 40~60mm | ±0.5 |
| 60~100mm | ±0.8 |
| 100mmUP | ±1.0 |



| REVISIONS | | | |
|-----------|-------------|------|----|
| REV | DESCRIPTION | DATE | BY |
| | | | |
| | | | |
| | | | |



| PART NO. | A | B |
|------------|------|-----|
| TP632-5 | 5.0 | 3.0 |
| TP632-5.5 | 5.5 | 3.5 |
| TP632-6 | 6.0 | 4.0 |
| TP632-6.3 | 6.3 | 4.0 |
| TP632-8 | 8.0 | 6.0 |
| TP632-9 | 9.0 | 6.0 |
| TP632-10 | 10.0 | 6.0 |
| TP632-11 | 11.0 | 6.0 |
| TP632-12 | 12.0 | 6.0 |
| TP632-12.7 | 12.7 | 6.0 |
| TP632-15.9 | 15.9 | 6.0 |
| TP632-19.1 | 19.1 | 6.0 |
| TP632-25.4 | 25.4 | 6.0 |
| TP632-31.8 | 31.8 | 6.0 |

Effective Fasten Length : B

NOTE:1. INNER THREAD WAS DONE BY 2ND PROCESS TAPING.
 SONE SLIGHT NYLON BURRS REMAINED INSIDE THE THREAD HOLE IS A NORMAL PHENOMENON.
 此為二次攻牙, 且因為尼龍材質緣故, 所以穴孔有些許尼龍屑, 屬正常現象.
 2. MADE OF EQUIVALENT MATERIAL.
 可使用同等材質

| | | | | | | |
|--|-------|----------------|-----|-----------|---|------------|
|  康揚企業股份有限公司 KANG YANG HARDWARE ENTERPRISE CO., LTD. 康揚塑膠(東莞)有限公司 KANG YANG PLASTIC(DONG GUAN) CO., LTD. 康哲電腦配件(吳江)有限公司 KANG CHEE COMPUTER COMPONENTS(WUJIANG) CO., LTD. | | | | TITLE | THREADED SPACER | SPEC. DWG. |
| | | | | MATERIAL | NYLON 66 UL94V-2 | DATE |
| PART NUMBER | | DRAWING NUMBER | | FINISH | DRAWN | |
| SEE ABOVE | | TP632-H | | NATURAL | JOHNNY | |
| SIZE | SCALE | UNIT | REV | COLOR | CHECK | |
| A4 | NONE | mm | B | NATURAL | 薛梅 | |
| UNLESS OTHERWISE SPECIFIED TOLERANCE | | | | SEE ABOVE | APPROVED | |
| | | | | |  | |